

## LISA

GB Mounting instructions

CZ Montážní návod

H Szerelési utasítás

RU Инструкция по монтажу

D/A Montageanleitung

PL Instrukcja montażu

RO Instrucțiuni de montaj


ES Manual de instrucciones












FR Notice de montage








NL Montage instructie

LT Montavimo instrukcija


SK Montážny návod



- 01 4x M12x40 
- 02 28x M12 
- 03 2x M12 
- 04 16x 6x20 
- 05 16x M10/19 
- 06 24x M12/23 
- 07 2x M12/36 
- 08 6x 
- 09 6x 
- 10 4x 
- 11 8x 

- 12 8x 8x40 
- 13 2x M10/23 
- 14 2x M10 
- 15 4x 
- 16 2x 
- 17 2x M10 
- 18 8x 4x40 


19 4x 520 


20 2x 110 

21 2x 





22 2x 

LISA		Steel profile length
Length	Width	X
150	70	1400
160	70	1500
170	70	1600






Assemble upside down on a soft mat.





GLUE GLUE NOT INCLUDED

Glue



D



E

